



Located in the Lee County  
Industrial Park  
5910 Clyde Rhyne Drive  
Sanford, NC 27330  
Office: (919) 776-5812  
Fax: (919) 774-4321  
WebSite: [www.ncst.org](http://www.ncst.org)

## Curriculum Schedule Spring 2008

**TEL 100 Basic Electricity R01**  
9 Days MTWThFMTWTh  
January 7-January 17, 2008 8:00-12:50  
Room T135 Instructor: Perry Emmons

**TEL 205 DMS 10 R01**  
9 Days TWThFMTWThF  
January 22-February 1, 2008 8:00-12:50  
Room T133 Instructor: Perry Emmons

**TEL 202 Cable Splicing R01**  
9 Days MTWThFMTWTh  
February 4-February 14, 2008 8:00-12:50  
Room T145 Instructor: Janet Gresham

**TEL 203 Cable Fault R01**  
6 Days FMTWThF  
February 15-February 22, 2008 8:00-12:50  
Room T135 Instructor: Perry Emmons

**TEL 106 Fiber Connectors R01**  
9 Days MTWThFMTWTh  
February 25-March 6, 2008 8:00-12:50  
Room T147 Instructor: Joe Horton

**TEL 105 Fiber Splicing R01**  
9 Days FMTWThFMTWTh  
March 7-March 19, 2008 8:00-12:50  
FOA EXAM Thursday - March 19, 2008  
Room T147 Instructor: Joe Horton

**TEL 200 Copper LAN R01**  
6 Days MTWThFM  
March 31-April 7, 2008 8:00-12:50  
Room T149 Instructor: Janet Gresham

**TEL 201 Station I & R R01**  
9 Days TWThFMTWThF  
April 8-April 18, 2008 8:00-12:50  
Room T145 Instructor: Janet Gresham

**TEL 108 Comdial (DX 80) R01**  
5 Days MTWThF  
April 21-April 25, 2008 8:00-2:30  
(40 MIN LUNCH)  
Room T133 Instructor: Perry Emmons

**TEL 209 ADSL R01**  
5 Days MTWThF  
April 28-May 2, 2008 8:00-2:30  
(40 MIN LUNCH)  
Room T135 Instructor: Perry Emmons

**REQUIREMENTS** - Must bring a TI-30Xa calculator to the following classes:  
Basic Electricity, DMS 10, Cable Splicing, Cable Fault Location, Comdial DX 80, ADSL.

**MUST WEAR BOOTS WITH A DEFINED HEEL** for Station Installation and Repair. A long sleeved shirt and leather work gloves are recommended.